

Need to Know-<u>Fall</u> Protection



FALL PROTECTION

PHOTO SOLICE: WWW OSHA GOV

PA OSHA CONSULTATION

## Remember....

- Fall protection/prevention is required for falls onto dangerous equipment (any height)
- Fall protection/prevention is required for work over 6' in height
- Fall protection/prevention is required for scaffolding over 10' in height
- Fall <u>arrest</u> anchor points must support:
  - o 5,000 lbs. per employee attached, or
  - Be designed by a qualified person to have at least a 2x safety factor
- Fall <u>restraint</u> anchor points must support at least 1,000 lbs. per employee attached
- The ABC's when using a personal fall arrest system
  - o Anchorage point
  - o **B**ody harness
  - <u>C</u>onnectors lanyards, deceleration devices, rope grabs, anchorage connectors

- Inspect body harnesses and lanyards:
  - o before use, and
  - at least annually (documented) by a Competent Person
- Harnesses and lanyards should never be modified
- Do not write on or paint harnesses and lanyards unless ink or paint is approved for use on the equipment
- Harnesses and lanyards should be taken out of service immediately if found to be defective or exposed to an fall/impact
- Whenever working with the potential of hanging by a harness for any length of time, a rescue plan must be in effect.